United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

This certificate reissued to replace certificate reported lost.

Number SA02702AT

This Certificate issued to

SERV-AERO ENGINEERING, INC. 37 MORTENSEN AVENUE SALINAS, CALIFORNIA 93905

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 4a of the Civil Aviation Regulations.

Original Product Type Certificate Number:

75 Series

Description of Type Design Change: Installation of an alternate oil cooler on aircraft previously modified by STC SA1540WE in accordance with Air Repair, Inc. "Installation Instruction for Rectangular Oil Cooler" Report No. 4000A, Rev. A, dated May 27, 2003, or later FAA approved revision.

Limitations and Conditions. This approval should not be incorporated in any aircraft of this model on which other previously approved modifications are incorporated, unless it is determined that the interrelationship between this installation and any previously approved modifications will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : May 7, 2003

Date reissued: September 20, 2007, May 15, 2008

Date of issuance: August 20, 2003

Date amended:

By direction of the Administrator

Manager, Technical and Administrative Support Los Angeles Aircraft Certification Office